


6.

Steering Control Adapter Ford Focus (98-04), Mondeo (00-03) Transit (<04), Transit Connect



If Problems: Check that correct adapter has been used and links are in the correct place. Always disconnect from the power supply if you change the head-unit adapter lead. Check that Red wire is 12V ignition and not Permanent power. Check that head-unit is earthed and black wire is earth. Check all connections are the same as the wiring diagram shown here

CHECK that the red wire is 12V IGNITION switch then turn on ignition

Test unit before fully fitting radio and trims back.